

## MANOR PARK CEMETERY CHAPEL

The chapel lobby walls had become cluttered with unnecessary fixtures and fittings, furniture was old and unfunctional. Leaking flat roofs had caused damage and staining to Bath stonework and plaster.

Working alongside the interior designer PAYE have transformed the space by removing the old unwanted fixtures and fittings, cleaning and repairing the masonry and painting it with Keim paint to help blend in the new repairs.

New ceilings have been installed incorporating a new lighting system together with new radiators, replacement plaster, French polished joinery and restored terrazzo flooring.